

3.600@Stratow=Godaty

Eng

本件等外格

JOHN ASHCROFT

FREDERICK A. BRUNNER

Director



Division of Energy

Division of Environmental Quality

Division of Geology and Land Survey

Division of Management Services

Division of Parks, Recreation,

and Historic Preservation

STATE OF MISSOURI DEPARTMENT OF NATURAL RESOURCES

DIVISION OF ENVIRONMENTAL QUALITY

St. Louis Regional Office 8460 Watson Road, Suite 217 St. Louis, MO 63119 314-849-1313

January 17, 1989

Mr. James Becker West County Disposal, Ltd. P.O. Box 428 Valley Park, MD 63088

Sile di Det Make LDE
IDW: MADONA POPORA
Break: LL 2
Others: AU 2
LEIN-BA

JAN & 3 1989

Wajte Манасежен? Билопана

Dear Mr. Becker:

Enclosed is a report of an inspection conducted by Mr. Bob Carlson of my staff. The report contains recommendations which the inspector has determined are warranted based on his findings at the facility.

Please review the report and implement the recommendations presented. Should you have any questions or comments, please contact me.

Sincerely,

ST. LOUIS REGIONAL OFFICE

Stuart Bean

Chief, Solid Waste Management Unit

SB:cj

Enclosure

/cc: Central Office - WMP

40249216

SUPERFUND RECORDS

DNR 0044

3.600 St. Louis County

West Count: . 11

Page 2

Gully erosion was observed on the western slope of the completed section of the landfill. Straw had been applied to the slope to slow the erosion process, but had apparently been less than completely effective. No waste was exposed in the gullies. Establishing vegetation may be necessary for better erosion control.

RECOMMENDATIONS

- 1. Cover leachate outbreak areas with a layer of compacted soil. Take appropriate measures to insure that leachate does not leave the site.
- 2. Reapply cover material in all eroded areas as needed.

Within 30 days please notify this office of actions taken to comply with the above recommendations. If there are any questions concerning this report, please feel free to contact Mr. Bob Carlson at (314) 849-1313.

APPROVED:

F. Donald Madgox

Regional Administrator

St. Louis Regional Office

FDM/BC/cj

PREPARED BY:

Bob Carlson

Environmental Specialist

St. Louis Regional Office

SOLID WASTE FACILITY INSPECTION REPORT

FACILITY

West County Disposal, Ltd., Sanitary Landfill St. Louis County MDNR Permit # 118911

INTRODUCTION

On January 11, 1989, an inspection of the above facility was conducted to assess compliance with the Missouri Solid Waste Management Law and Regulations. Mr. Bob Carlson, Environmental Specialist, represented the Missouri Department of Natural Resources. Mr. Jim Lacocq represented the facility.

FINDINGS

- 1. Filling was occurring in the wet-weather area in the northeast section.
- A leachate outbreak was observed at the base of the slope at the northwest corner of the landfill.
- 3. Cover material had eroded in the new fill area at the north end of the site.
- 4. Gully erosion had occurred on the western slope of the landfill.

DISCUSSION

Due to rains during and in the days previous to the inspection, filling operations were being conducted in the northeast section of the older landfill area, which had not yet reached its final permitted elevation. This area is more accessible during wet weather.

Ponded leachate was observed at the base of the landfill slope in the northwest section of the site. Mr. Lacocq stated that the outbreak had been ongoing for a few days, and that it would be capped as soon as conditions were dry enough to use the earth-moving vehicles in the area. The leachate and ponded rainwater were in a semi-frozen state, and were not likely to migrate off site in any case.

Previously applied cover material had eroded in the new fill area to the north, exposing some waste. Mr. Lacocq said that this would also be remedied when the area dried out enough, which he estimated to be a day or two. He said that the temporary road to the area would be improved with a layer of gravel as soon as possible.

MISSOURI DEPARTMENT OF NATURAL RESOURCES Division of Environmental Quality

D	ate: 1-11-89	BANI			Days/Week Open:	, ,		
. и	ame of Sanitary Landfill:_	Wes	+ Count	y Disp	osal, Ltd. Santary La	ndf	<u> </u>	
	ermit No.: [[891]			•	•			
c	wher: West County Dispos	إساست	Ltd.		Operator: (Same)		
2	ddress: P.o. Box 428				Address:			
	Valley Park, M	0 6	3088					
3	. Remaining Life of Landf:				Permittee: (Same			
	A. Estimated quantity of	tons/	ite acces /wk.	pted,	Address:			
•	B. Estimated life of recapproved by engineer: 8-10 yrs.			£111	Phone: (314) 225-73	20		
·	If necessary, describe	אטיי.	s" viola	tions un	UNS-Unsatisfactory; or NA-1 der "Remarks".		•	
	id farmit tisuance, Special Operating	At.	164 4/7	151(2)3.	Operating samuel eventable to employees	 	Up &	- H.A
151131	had Permit Egemptions Authorization to operate obtained prior to systemate of yeste.		\ \ \	(6116)).	boundary mercers, benchmarks, horisontal control stations and construction stakes		<u> </u>	
33(2) 1 328 40-2.	Site constructed and operated per approved terms and conditions of sermit. Full contities solid Maste Technicians.	Y		(65(252.	marked and identified. Nissing or displaced benimests or horizontal control stations replaced or	<u> </u>		
(A)	file specified by a cortified solid vaste technician to cory Terry Africa	>		(4)(C)3.	re-perabitahed. Missing of displaced construction istakes replaced of re-established			
<u>9 230 30-1.</u> 11(51:.	Ty injecty Landilla Dasign and Operation Builty solid weath series erashed on solid ground and pushed onto working face hear bottom	1		(ench.	Second biles to Localaine emposization sectors as uncedents.			7
214012.	inal; dead animals covered identification	7		(4)(5)5.	Construction states earlied the active			
3)(¢)1.	The disposal of special waste approved in the permit conducted in accordance	7	 	— । गताः	eres placed prior to deposition of vests in individual eress. Surface watercourses and rungif property	-{	 ,	1
(3) (C) 2.A.	with speroved design and plans. Written approved from the department obtained for special waste not approved	V		-	diverted from the landfill. Senttery landfill construction and grading to promote tapid surface valor runoff		/	
(3)(6)3.8.	in permit. Approved special waste disposed of	7	 	ागाला.	Contact with solid waste shell be	1	<u> </u>	
ingen.	sign posted at entrance listing empluded wattr.	Ż		नात्यः	Leachate collection system property leachate and operated to eccordance	了	-	
(3)(6)4.	Procedure for ecreening and removal of excluded weater.	J]	173(6)4.	Liner constructed in accordance with	┤╧┉		·
(3)(6)1.	covered with four feet of competted	1		(7)(e)\$.	epproved dealer epecifications. Leachete generated en-site controlled	-	<u> </u>	

(2)(0)2. 111671. (3)(6)2. issieis. (3)(8)). (3)(6)4. (3)(6)3 totl. Exclude wasten listed in subsection [381A] of this rule shall not be on-eite and not allowed to discharge off the samitary landfill or discharge into waters of the state. Leachate and swoolf managed in accordan with the Missouri Clean Water Law and 1351614. (3)(A) of this rule shell not be expected for discovery to active the state excessible in all weather conditions. Temporary roads provided for delivery to working feto.
If access roads or public roads are tieded, sixerable sabitary landfill in dwallable. Construction and operation of the site is confused in excertance with indicated in excertance with indicated in excertance with indicated for the special section of the site is confused in excertance with indicated in excertance with indicated between site operations and property boundary. (7)(6)6. (4)(C)L. Graundwater controlling vells installed tericit.A. Groundwater controlling wells installed per approved blans.
Groundwater controlling wells operational prior to acceptance of waste, unless other arrangements are approved.
Burning of fells waste prohibited unless a burning permit is obtained from the department or, when appropriate, total (4)(C12. (6)(C)1.3. (8)(C) (Bifers. 1 opperconn control agency.

Decomposition and control agences

Leptenented on necessary to prevent

migration and accusation. (\$) (C) 3. (10)(C)L. PROPERTY BOUNGARY.

 -		145	2005	9/4	·		iAT T	THE P	1757
	Secomposition has not stated to concentrate in Swe' alto above	1		- 8: 4		Regrading and recovering of y to	<u> </u>	7	,
25(213.3)	CHARGESTUR DEFCENT - SECTIONS CO	<u> </u>			mier.	BOFFOW areas reclaimed in accordance with	1	-7	
	concentrate in the soil at the property boundary above five percent LEE for	1			1	Adequate solid waste handling equipment	Z		•
231213.	Cecomposition des monttering results					Bolld waste to be competted, spread to layers no more than two feet thick and	.71		
	ty permit.		i		!	confined to smallest practical ages.	<u> </u>		
231234.	Landfill operated to compliance with applicable requirements of Chapter \$4).	/			<u> </u>	voluse,	\mathcal{L}		
	19374 404 Pules.	V		ł	(14)(C)2.	Caver compected es much to precitat. Preventive melatement performed un	-~,		<u> </u>
LHCI	Ascros courses brodseen refrances apea				ቼ _ ````	erylpment.			
hicit.	hocestory. Litter santrol devices utilized near		 	 	(14)(6)).	Solid waste not disposed of in vater to			1
	working face and alsowhere as meeded.	,	ļ .	1	h	causing enequity breeding proples.			L_
	Litter cullected from fences, and the ground surface, and incorporated into the		}		(ISHC)L.	Fire entinguishers provided on all solid waste handling e-respond			
	ective call at the end of each day or		1	1	(15)(C)1.	All fires in wastes being delivered to	<u> </u>		1
žitčia.	Vences essily moved by mind covered as					the site or which decor at the working face or within equipment entlanguished.	·/	ļ	1
.,,,,,,,,	necessary to prevent their betching			ì	(11)(6)).	Comminications equipment evaluable.		 	┼──
	atrborne end scettered.	_	<u> </u>	i	tisticia.	Scavenoing erobiotted.		1	\
1)(6)1.	un-site vegetation Cleared only 48	7		Γ	(18)(c)s.	Controlled access to alle by setablished roadways and limited to hours when		Π	T -
12)(C)4.	Salvaged materials removed daily or	,	\ 		┪	specesing personnel are on duty.	<u> </u>	1	
	etored in assistically acceptable conceiners or enclosures.	\	1	i	(15)(c) 6.	Freffle controlled and directed to	ΓZ		
31(6)1.	Cover spelled at the end of each			+	1131637.	distinguish disposing emints. Sits dust controlled for safety purposes	 * ,	┾─	
,,,,,,,,,	operating day requestions of weather in a	and of wanther to a	land to meauage auteaness	1 /	1	1			
	compacted layer not lass than sim			1	(16)(C)1.A.	Records of major problems and complaints	17	7	<u> </u>
	inches thick, Cover material available .	~	l l		17	isaletainet.	<u> ~</u>	╄.	↓
(13)(C)2.	Cover applied to completed erass of the	completed erass of the teachete sample	-{	-	1,10,10,1.0.	Monitoring records maintained: a. leachete sampling and analyses.	1 /	1	1
	landfill idle more than 60 days in a					b. ges sempling and madyses,	\		l l
	compacted layer not less than one foot		C. ground and surface water analyses.		<u>.</u>	L.			
	th ten.	<u> </u>		↓	116)(c)1.c.	gecords of vector courses ellosts	$\mathbf{L}Z$		T T
13)(C)3.	Cover applied to completed areas of the landfill in a compacted layer not less	į .	1	1 ,	TENCH.O.	Becords of duet and litter control	· - Ŭ-	-1	-]
	then two feet thick overlein by at least		1	1	(10)(0)1.0.	offorts maintained.	10	1	i i
	one foot of soil, as required, Capable of supporting vegetation.	יין		1	(16)(0)1.8.	Records of quentity of wests handled	1		1-
11)(6)4.	Final side slopes not to exceed 33 1/3	ノ	·}	·}	(IL)(C)L.F.	Ascords of description, sources and	ナラ	+	1—
Dittis.	Vegetation established within one hundred	_	┦			volume of special wastes listed to subsection (1)(A) saintained.	1	1	1
mileis.	and eighty days of application or regrading of cover required by (13)(C)2.	1/	1	1		TAMASSTON TITAL SPINISTURG.	1	-1	
	and 3.	<u> </u>	.						

•		
		
		
<u>`</u>		
		<u></u>
	· · · · · · · · · · · · · · · · · · ·	
	•	
•	BY:	ma a ci
		Signature of Inspector
	OFFICE:	SLRE

τ. ,